



3750 West Indian School Road
Phoenix, Arizona 85019-3518
(602) 636-6720
(800) 644-9131
(602) 636-6724 Fax
www.xcelsurfaces.com

TECHNICAL DATA SHEET- BUBBLE GUM RELEASE

DESCRIPTION AND USE

BUBBLE GUM RELEASE is a colorless liquid releasing agent specially designed to be used to eliminate overlay residue build-up on stamping mats and texturing tools so they remain flexible and maximize the life of the tools. Bubble Gum Release provides a lubricating film that decreases the friction between cementitious overlayment and the stamp mats

ADVANTAGES

- Evaporates quickly; provides superior impression transfer.
- Can be tinted with dry iron oxide pigments to produce highlights in stamped overlayment.

APPLICATION

Using a pump-type sprayer, apply a light coat of Bubble Gum Release to both the surface of the overlayment and the imprinting tool. Apply only to a small (10-15 sq. ft.) area that is ready to be stamped. If applied to a large area it will evaporate before the surface can be textured. Never trowel or mix the release into the overlayment. Typical evaporation time is 1-2 hours.

COVERAGE

Approximately 250-300 sq. ft. per gallon

PACKAGING

1&5 gallon containers

CAUTION

COMBUSTABLE- Keep away from heat sparks and flames. To avoid breathing vapors use only with adequate ventilation. When using in an interior space it is advisable to wear an appropriate cartridge type (NIOSH/MSHA TC 23C or equivalent). Close container after each use. Avoid contact with skin. VOC content is less 400 grams per liter. Keep out of reach of children.

HANDLING & STORAGE

Read Material Safety Data Sheets before using. Dispose of unused material in accordance with Federal, State and Local regulations. Storage temperature: (45°-85° F). Do not let Product Freeze.

Xcel Surfaces products are intended for professional use only. Keep away from children. Xcel Surfaces warrants its products to be free of manufacturing defects and that they will meet the current published physical properties when applied in accordance with Xcel Surfaces directions and tested in accordance with ASTM and Xcel Surfaces standards. There are no other warranties by Xcel Surfaces of any nature whatsoever expressed or implied, including any warranty of merchantability or fitness for a particular purpose in connection with this product. Xcel Surfaces shall not be liable for damages of any sort, including remote or consequential damages resulting from any claimed breach of any warranty, whether expressed or implied, including any warranty of merchantability or fitness for a particular purpose or from any cause whatsoever. Xcel Surfaces shall also not be responsible for use of this product in a manner to infringe on any patent held by others.

© XCEL SURFACES 2008
All rights reserved. Made in the USA

Xcel Surfaces Bubble Gum Release